



To

The Principal

Baldwin Farm Area High School

Kadma, Jamshedpur.

Sub: Fire Safety Audit report

As per your request letter number BFA/63/24 dated 12.03.2024, Fire Safety Audit was conducted by Tata Steel Fire Service personnel on 19.03.2024. Observations observed during the audit are as follows:

1. The school building has two staircases.
2. Every classroom has two doors.
3. Corridor is of sufficient width.
4. Sand buckets are placed at appropriate points.
5. Sufficient number of Fire extinguishers are available for each floor as per IS 2190:2010.
6. Exit route is mapped and marked properly.
7. Emergency Assembly point is marked.
8. Emergency siren is installed for emergency purpose.
9. Fire Evacuation drill are conducted.
10. Electrical Panel room protected with DCP Modular system.

Baldwin Farm Area High School, Kadma, Jamshedpur meet the fire safety norms.

Thanking you,


Rakesh Joshi

Head Fire Brigade

Tata Steel Fire Services.

**HEAD
FIRE BRIGADE**

TATA STEEL

The Tata Iron and Steel Company Limited
Jamshedpur 831 001 India

Regd Office Bombay House 24 Homi Mody Street Mumbai 400 001